

SERVICE LETTER



January 10, 2011

SL2011-1

TITLE

ISSUE OF BOM100 BLADE OVERHAUL MANUAL REVISION 5

TO:

FAA-Approved Propeller Repair Stations, Aircraft Manufacturers, Owners and Operators

EFFECTIVITY

BOM100, Blade Overhaul Manual

REASON

This Service Letter announces the release of the McCauley Blade Overhaul Manual BOM100 Revision 5.

DESCRIPTION

The Blade Overhaul Manual BOM100 Revision 5 will be available for purchase on January 18. This manual becomes mandatory on March 1, 2011.

Current subscribers to these manuals will have the revisions mailed on or about January 18, 2011.

McCauley Propeller Systems
Department 569
PO Box 7706
Wichita, KS 67277-7706
U.S.A
Phone: 316-517-5800
Fax: 316-517-7271

McCauley Product Support - Phone: 316-831-4021

APPROVAL

FAA approval has been obtained on technical data in this publication that affects product type design.

January 10, 2011

Page 1 of 1

TO OBTAIN SATISFACTORY RESULTS, PROCEDURES SPECIFIED IN THIS SERVICE INFORMATION MUST BE ACCOMPLISHED IN ACCORDANCE WITH ACCEPTED METHODS AND PREVAILING GOVERNMENT REGULATIONS. MCCAULEY PROPELLER SYSTEMS CANNOT BE RESPONSIBLE FOR THE QUALITY OF WORK PERFORMED IN ACCOMPLISHING THIS SERVICE INFORMATION.

McCauley Propeller Systems
PO Box 7704
Wichita, Kansas 67277-7704